1887264
O-Hampton Side Table
Parts and Hardware List

A.	Top Assembly	1 pc
B.	Bottom Assembly	1 pc
C.	Blocks	4 pcs
D.	Spindles	8 pcs
E.	Feet	4 pcs
F.	Allen Head Bolts	8 pcs
G.	Flat Washers	8 pcs
H.	Lock Washers	8 pcs
I.	Phillips Head Screws	4 pcs
J.	Phillips Head Screwdriver	1 pc
K.	Allen Head Wrench	1 pc
L.	Optional Allen Head Screwdriver Bit	1 pc

* Please make sure that you have all the parts and hardware indicated above before you begin assembly of this item.
* This item should be assembled on a soft surface to prevent scratching the finish during assembly.
* This item may require periodic tightening.
* Take care not to overtighten bolts if using supplied Allen Head Screwdriver Bit.

Hardware Illustrations



F. Allen Head Bolt



H. Lock Washer



G. Flat Washer



I. Phillips Head Screw

1887264
O-Hampton Side Table

Assembly Instructions

1. **Attach Spindles (D) to Top Assembly (A)** Put the Top Assembly (A) upside down on a soft surface. Align the exposed threads of Spindles (D) with the pre-threaded holes in the blocks of Top Assembly (A). Tighten by turning in a clockwise direction. See Illustration.
2. **Attach Blocks (C) and Bottom Assembly (B)** Align the pre-drilled holes in the Blocks (C) with the pre-threaded holes in the Spindles (D) and the pre-drilled holes in the Bottom Assembly (B). Make sure the finished surfaces of Bottom Assembly (B)) and Blocks (C) face the Top Assembly (A). Insert Allen Head Bolts (F), Lock Washers (H) and Flat Washers (G) through the holes of Bottom Assembly (B) and Blocks (C) into the pre-threaded holes in the Spindles (D). Secure with Allen Head Tool (K or L). See Illustration.
3. **Attach Feet (E)** Align the exposed threads of Feet (E) with the pre-threaded holes in the Bottom Assembly (B).Tighten by turning in a clockwise direction as illustration. (Do not overtighten the feet). Secure the Feet (E) to the Bottom Assembly (B) with Phillips Head Screws (I) using Phillips Head Screwdriver (J). See Illustration.